

### *Photographic Progress Works*

**PROJECT:** RENOVATION RIVER GARDEN



**CONSULTANT:** Northcroft (Thailand) Ltd.

**LOCATION:** Charoen Krung 42/1, Bangkok

**CONTRACTOR:** Green EPC Co.,Ltd.

**ACTIVITIES ON SITE:** Electrical Work

**PERIOD :** 29 November 2019


	
<b>Activity</b>	<b>Activity</b>
Installation Main Pipe Emer+Alarm	Installation Wire Way
Floor 9-10 (Corridor)	Floor 13 (Corridor)
<b>Date :</b> 29 November 2019	<b>Date :</b> 29 November 2019


<b>Activity</b>	<b>Activity</b>
<b>Date :</b>	<b>Date :</b>

*Photographic Progress Works*

**PROJECT:** RENOVATION RIVER GARDEN  
**LOCATION:** Charoen Krung 42/1, Bangkok  
**ACTIVITIES ON SITE:** Sanitary and Fire Protection Work

**CONSULTANT:** Northcroft (Thailand) Ltd.  
**CONTRACTOR:** Green EPC Co.,Ltd.  
**PERIOD :** 29 November 2019

			
<b>Activity</b>		<b>Activity</b>	
Edit Maine Sprinkler SPK Work		Installation Maine Sprinkler SPK Work	
Floor 13		Floor 8	
<b>Date :</b>	29 November 2019	<b>Date :</b>	29 November 2019

			
<b>Activity</b>		<b>Activity</b>	
Installation Maine CW,HWS			
Floor 13			
<b>Date :</b>	29 November 2019	<b>Date :</b>	

*Photographic Progress Works*

**PROJECT:** RENOVATION RIVER GARDEN

**CONSULTANT:** Northcroft (Thailand) Ltd.



**LOCATION:** Charoen Krung 42/1, Bangkok

**CONTRACTOR:** Green EPC Co.,Ltd.

**ACTIVITIES ON SITE:** Air Conditioning Work

**PERIOD :** 29 November 2019

			
<b>Activity</b>		<b>Activity</b>	
Installation Ducts Pipe Work		Installation Ducts Pipe Work	
Floor 11 (Corridor)		Floor 11 (Corridor)	
<b>Date :</b> 29 November 2019		<b>Date :</b> 17 February 2017	



			
<b>Activity</b>		<b>Activity</b>	
Installation Ducts Pipe Work		Keep Work Ducts Pipe and Solution Pipe	
Floor 11 (Corridor)		Floor 14-15 (Corridor)	
<b>Date :</b> 29 November 2019		<b>Date :</b> 29 November 2019	





*Photographic Progress Works*

**PROJECT:** RENOVATION RIVER GARDEN  
**LOCATION:** Charoen Krung 42/1, Bangkok  
**ACTIVITIES ON SITE:** Air Conditioning Work

**CONSULTANT:** Northcroft (Thailand) Ltd.  
**CONTRACTOR:** Green EPC Co.,Ltd.  
**PERIOD :** 29 November 2019

			
<b>Activity</b>		<b>Activity</b>	
Keep Work Ducts Pipe and Solution Pipe		Keep Work Ducts Pipe and Solution Pipe	
Floor 14-15 (Corridor)		Floor 14-15 (Corridor)	
<b>Date :</b>	29 November 2019	<b>Date :</b>	29 November 2019


			
<b>Activity</b>		<b>Activity</b>	
Installation Solution Pipe Work		Installation Solution Pipe Work	
Floor 8-9 (Corridor)		Floor 8-9 (Corridor)	
<b>Date :</b>	29 November 2019	<b>Date :</b>	29 November 2019

### *Photographic Progress Works*

**PROJECT:** RENOVATION RIVER GARDEN  
**LOCATION:** Charoen Krung 42/1, Bangkok  
**ACTIVITIES ON SITE:** Air Conditioning Work

**CONSULTANT:** Northcroft (Thailand) Ltd.  
**CONTRACTOR:** Green EPC Co.,Ltd.  
**PERIOD :** 29 November 2019

	
<b>Activity</b>	<b>Activity</b>
Installation Solution Pipe Work	Installation Solution Pipe Work
Floor 8-9 (Corridor)	Floor 8-9 (Corridor)
<b>Date :</b> 29 November 2019	<b>Date :</b> 29 November 2019

	
<b>Activity</b>	<b>Activity</b>
Installation Solution Pipe Work	
Floor 8-9 (Corridor)	
<b>Date :</b> 29 November 2019	<b>Date :</b>