

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN



CONSULTANT: Northcroft (Thailand) Ltd.



LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Electrical Work

PERIOD : 2 December 2019

			
Activity		Activity	
Installation Wire Way		Installation Main Pipe Emer+Alarm	
Floor 13 (Corridor)		Floor 9-11	
Date : 2 December 2019		Date : 2 December 2019	

			
Activity		Activity	
Installation Wire Way		Installation Wire Way	
Floor 13 (Corridor)		Floor 13 (Corridor)	
Date : 2 December 2019		Date : 2 December 2019	

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN


CONSULTANT: Northcroft (Thailand) Ltd.

LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Sanitary and Fire Protection Work

PERIOD : 02 December 2019




Activity

Edit Maine Sprinkler Pipe Work

Floor 11

Date : 2 December 2019



Activity

Edit Maine Sprinkler Pipe Work

Floor 11

Date : 2 December 2019



Activity

Installation Maine Pipe CW,HWS Work

Floor 8-12

Date : 2 December 2019



Activity

Preparation the Maine Pipe CW,HWS Work

Floor P3 (Store)

Date : 2 December 2019

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN



CONSULTANT: Northcroft (Thailand) Ltd.



LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Air Conditioning Work

PERIOD : 02 December 2019

			
Activity		Activity	
Pipe Insulation Work		Copper pipe welding Work	
Floor 9		Floor 9	
Date :	2 December 2019	Date :	2 December 2019

			
Activity		Activity	
Pipe Insulation Work		Pipe Insulation Work	
Floor 8		Floor 8	
Date :	2 December 2019	Date :	2 December 2019