

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN



CONSULTANT: Northcroft (Thailand) Ltd.



LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Electrical Work

PERIOD : 03 December 2019



	
Activity	Activity
Cleaning	Installation Main Pipe Emer+Alarm
Floor 6	Floor 7
Date :	Date :
3 December 2019	3 December 2019



	
Activity	Activity
Cleaning	Cleaning
Floor 6	Floor 6
Date :	Date :
3 December 2019	3 December 2019

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Sanitary and Fire Protection Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 03 December 2019

	
Activity	Activity
Preparation the Main Pipe CW,HWS Work	Assemble main pipe CW,HWS
Floor 8-12	Floor 8-12
Date : 3 December 2019	Date : 3 December 2019

	
Activity	Activity
Modify Main Pipe SPK Work	Modify Main Pipe SPK Work
Floor 14	Floor 14
Date : 3 December 2019	Date : 3 December 2019

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN

CONSULTANT: Northcroft (Thailand) Ltd.



LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Air Conditioning Work

PERIOD : 03 December 2019

	
Activity	Activity
Hanging Support Work	Copper pipe welding Work
Floor 9	Floor 9
Date : 3 December 2019	Date : 3 December 2019

	
Activity	Activity
Pipe Insulation Work	Pipe Insulation Work
Floor 9	Floor 9
Date : 3 December 2019	Date : 3 December 2019