

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN



CONSULTANT: Northcroft (Thailand) Ltd.



LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Electrical Work

PERIOD : 04 December 2019



			
Activity		Activity	
เดินท่อเมนไฟฟ้า Emer+Alarm		เดินท่อเมนไฟฟ้า Emer+Alarm	
Floor 11		Floor 11	
Date :	4 December 2019	Date :	4 December 2019



			
Activity		Activity	
เดินท่อเมนไฟฟ้า Emer+Alarm		เดินท่อเมนไฟฟ้า Emer+Alarm	
Floor 11		Floor 11	
Date :	4 December 2019	Date :	4 December 2019

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Sanitary and Fire Protection Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 04 December 2019

			
Activity		Activity	
งานแก้ไขท่อเมน SPK		งานแก้ไขท่อเมน SPK	
Floor 14		Floor 14	
Date :	4 December 2019	Date :	4 December 2019

			
Activity		Activity	
งานติดตั้งท่อเมน CW,HWS		งานติดตั้งท่อเมน CW,HWS	
Floor 8-12		Floor 8-12	
Date :	4 December 2019	Date :	4 December 2019

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN

CONSULTANT: Northcroft (Thailand) Ltd.


LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Air Conditioning Work

PERIOD : 04 December 2019

			
Activity		Activity	
ติดตั้งท่อ Duct		ติดตั้งท่อ Duct	
Floor 11		Floor 11	
Date :	4 December 2019	Date :	4 December 2019

			
Activity		Activity	
ติดตั้งท่อ Duct			
Floor 11			
Date :	4 December 2019	Date :	