

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN



CONSULTANT: Northcroft (Thailand) Ltd.


LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Air Conditioning Work

PERIOD : 9 March 2020

			
Activity		Activity	
เก็บงานท่อคัทสึ		เก็บงานท่อคัทสึ	
Floor 07		Floor 07	
Date : 9 March 2563		Date : 9 March 2563	

			
Activity		Activity	
เก็บงานท่อคัทสึ			
Floor 07			
Date : 9 March 2563		Date :	

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN



CONSULTANT: Northcroft (Thailand) Ltd.



LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Sanitary and Fire Protection Work

PERIOD : 9 March 2020

	
Activity	Activity
ทดสอบรอยรั่ว SPK	ทดสอบรอยรั่ว SPK
Floor 13,14	Floor 13,14
Date : 9 March 2563	Date : 9 March 2563

	
Activity	Activity
มาร์กตำแหน่งท่อ CW,HWS,HWR	มาร์กตำแหน่งท่อ CW,HWS,HWR
Floor 6-16	Floor 6-16
Date : 9 March 2563	Date : 9 March 2563