

### *Photographic Progress Works*

**PROJECT:** RENOVATION RIVER GARDEN



**CONSULTANT:** Northcroft (Thailand) Ltd.



**LOCATION:** Charoen Krung 42/1, Bangkok

**CONTRACTOR:** Green EPC Co.,Ltd.

**ACTIVITIES ON SITE:** Electrical Work

**PERIOD :** 24 August 2020

	
<b>Activity</b>	<b>Activity</b>
Installation of Electrical Pipe Above the ceiling for the Room.	Installation of Electrical Pipe Above the ceiling for the Room.
Floor 12	Floor 12
<b>Date :</b> 24 August 2563	<b>Date :</b> 24 August 2563

	
<b>Activity</b>	<b>Activity</b>
Installation of Electrical Pipe Above the ceiling for the Room.	Installation of Electrical Pipe Above the ceiling for the Room.
Floor12	Floor12
<b>Date :</b> 24 August 2563	<b>Date :</b> 24 August 2563

### *Photographic Progress Works*

**PROJECT:** RENOVATION RIVER GARDEN  
**LOCATION:** Charoen Krung 42/1, Bangkok  
**ACTIVITIES ON SITE:** Sanitaly And Fire Protection Work

**CONSULTANT:** Northcroft (Thailand) Ltd.  
**CONTRACTOR:** Green EPC Co.,Ltd.  
**PERIOD :** 24 August 2020


	
<b>Activity</b>	<b>Activity</b>
Prepare work Installation Pipe CW,HW Area Shaft.	Prepare work Installation Pipe CW,HW Area Shaft.
Floor 15-16	Floor 15-16
<b>Date :</b> 24 August 2563	<b>Date :</b> 24 August 2563

<b>Activity</b>	<b>Activity</b>
<b>Date :</b>	<b>Date :</b>

### *Photographic Progress Works*

**PROJECT:** RENOVATION RIVER GARDEN  
**LOCATION:** Charoen Krung 42/1, Bangkok  
**ACTIVITIES ON SITE:** Air Conditioning Work

**CONSULTANT:** Northcroft (Thailand) Ltd.  
**CONTRACTOR:** Green EPC Co.,Ltd.  
**PERIOD :** 24 August 2020

	
<b>Activity</b>	<b>Activity</b>
Installation Duct Air Conditioner.	
Floor 16	
<b>Date :</b> 24 August 2563	<b>Date :</b>

<b>Activity</b>	<b>Activity</b>
<b>Date :</b>	<b>Date :</b>