

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN



CONSULTANT: Northcroft (Thailand) Ltd.



LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Electrical Work

PERIOD : 03 September 2020



	
Activity	Activity
Installation of Electrical Pipe Above the ceiling for the Room.	Installation of Electrical Pipe Above the ceiling for the Room.
Floor 10	Floor 10
Date : 3 September 2563	Date : 3 September 2563



	
Activity	Activity
Installation of Electrical Pipe Above the ceiling for the Room.	Installation of Electrical Pipe Above the ceiling for the Room.
Floor 12	Floor 10
Date : 3 September 2563	Date : 3 September 2563

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Sanitary And Fire Protection Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 03 September 2020



	
Activity	Activity
HWR,HWS Pipe Insulation in Shaft Area .	HWR,HWS Pipe Insulation in Shaft Area .
Floor 13-16	Floor 13-16
Date : 3 September 2563	Date : 3 September 2563



	
Activity	Activity
HWR,HWS Pipe Insulation in Shaft Area .	HWR,HWS Pipe Insulation in Shaft Area .
Floor 13-16	Floor 13-16
Date : 3 September 2563	Date : 3 September 2563

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Electrical Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 03 September 2020

	
Activity	Activity
Installation of Electrical Pipe Above the ceiling for the Room.	Installation of Electrical Pipe Above the ceiling for the Room.
Floor 12	Floor 10
Date : 3 September 2563	Date : 3 September 2563

	
Activity	Activity
Installation of Electrical Pipe Above the ceiling for the Room.	Installation of Electrical Pipe Above the ceiling for the Room.
Floor 10	Floor 12
Date : 3 September 2563	Date : 3 September 2563

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN



CONSULTANT: Northcroft (Thailand) Ltd.


LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Air Conditioning Work

PERIOD : 03 September 2020

	
Activity	Activity
Installation of Duct Pipe	Installation of Duct Pipe
Floor 16	Floor 16
Date : 3 September 2563	Date : 3 September 2563

	
Activity	Activity
Installation of Reagent Pipe	
Floor 16	
Date : 3 September 2563	Date :

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN



CONSULTANT: Northcroft (Thailand) Ltd.



LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Electrical Work

PERIOD : 03 September 2020

	
Activity	Activity
Installation of Electrical Pipe Above the ceiling for the Room.	Installation of Electrical Pipe Above the ceiling for the Room.
Floor 10	Floor 10
Date : 3 September 2563	Date : 3 September 2563

	
Activity	Activity
Installation of Electrical Pipe Above the ceiling for the Room.	Installation of Electrical Pipe Above the ceiling for the Room.
Floor 12	Floor 12
Date : 3 September 2563	Date : 3 September 2563