

Photographic Progress Works


PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Sanitary And Fire Protection Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 08 September 2020



| |
|------------------------------------|
| Activity |
| Hold the support work in the shaft |
| Floor 6-16 |
| |
| Date : 8 September 2563 |

| |
|------------------------------------|
| Activity |
| Hold the support work in the shaft |
| Floor 6-16 |
| |
| Date : 8 September 2563 |



| |
|------------------------------------|
| Activity |
| Hold the support work in the shaft |
| Floor 6-16 |
| |
| Date : 8 September 2563 |

| |
|---------------------------------------|
| Activity |
| Installation CW,HW Pipe Area Corridor |
| Floor 16 |
| |
| Date : 8 September 2563 |

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN


CONSULTANT: Northcroft (Thailand) Ltd.

LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Sanitaly And Fire Protection Work

PERIOD : 08 September 2020

| | | | |
|--|------------------|-----------------|--|
|  | | | |
| Activity | | Activity | |
| Installation CW,HW Pipe Area Corridor | | | |
| Floor 16 | | | |
| Date : | 8 September 2563 | Date : | |

| | | | |
|-----------------|--|-----------------|--|
| Activity | | Activity | |
| | | | |
| | | | |
| Date : | | Date : | |

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN



CONSULTANT: Northcroft (Thailand) Ltd.

LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.



ACTIVITIES ON SITE: Electrical Work

PERIOD : 08 September 2020



| |
|---|
| Activity |
| Installation of Electrical Pipe Above the ceiling for the Room. |
| Floor 13 |
| |
| Date : 8 September 2563 |

| |
|---|
| Activity |
| Installation of Electrical Pipe Above the ceiling for the Room. |
| Floor 13 |
| |
| Date : 8 September 2563 |




| |
|---|
| Activity |
| Installation of Electrical Pipe Above the ceiling for the Room. |
| Floor 14 |
| |
| Date : 8 September 2563 |

| |
|---|
| Activity |
| Installation of Electrical Pipe Above the ceiling for the Room. |
| Floor 14 |
| |
| Date : 8 September 2563 |

Photographic Progress Works



PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Electrical Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 08 September 2020



| | |
|---|------------------|
| Activity | |
| Installation of Electrical Pipe Above the ceiling for the Room. | |
| Floor 14 | |
| | |
| Date : | 8 September 2563 |

| | |
|---|------------------|
| Activity | |
| Installation of Electrical Pipe Above the ceiling for the Room. | |
| Floor 14 | |
| | |
| Date : | 8 September 2563 |



| | |
|---|------------------|
| Activity | |
| Installation of Electrical Pipe Above the ceiling for the Room. | |
| Floor 14 | |
| | |
| Date : | 8 September 2563 |

| | |
|-----------------|--|
| Activity | |
| | |
| | |
| Date : | |