

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN


CONSULTANT: Northcroft (Thailand) Ltd.

LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.



ACTIVITIES ON SITE: Electrical Work

PERIOD : 11 September 2020



Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 13	
Date :	11 September 2563

Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 13	
Date :	11 September 2563



Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 13	
Date :	11 September 2563

Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 13	
Date :	11 September 2563

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN


CONSULTANT: Northcroft (Thailand) Ltd.

LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.


ACTIVITIES ON SITE: Electrical Work

PERIOD : 11 September 2020



Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 13	
Date :	11 September 2563

Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 13	
Date :	11 September 2563





Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 13	
Date :	11 September 2563

Activity	
Wiring the Electrical System for the Mock up Room No.24	
Floor 08	
Date :	11 September 2563

Photographic Progress Works



PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Air Conditioning Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 11 September 2020



Activity
Fix the Installation Ductwork.
Floor 08
Date : 11 September 2563

Activity
Fix the Installation Ductwork.
Floor 08
Date : 11 September 2563




Activity
Fix the Installation Ductwork.
Floor 08
Date : 11 September 2563

Activity
Installation Air Conditioned Sewer for Mocku p Room No.24
Floor 08
Date : 11 September 2563

Photographic Progress Works


PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Sanitary and Fire Protection Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 11 September 2020



Activity	
Installation CW,HW Pipe Area Corridor.	
Floor 12	
Date :	11 September 2563

Activity	
Installation CW,HW Pipe Area Corridor.	
Floor 12	
Date :	11 September 2563



Activity	
Installation the Pipe Holder	
Floor 6-16	
Date :	11 September 2563

Activity	
Installation the Pipe Holder	
Floor 6-16	
Date :	11 September 2563