



*Photographic Progress Works*



**PROJECT:** RENOVATION RIVER GARDEN  
**LOCATION:** Charoen Krung 42/1, Bangkok  
**ACTIVITIES ON SITE:** Electrical Work

**CONSULTANT:** Northcroft (Thailand) Ltd.  
**CONTRACTOR:** Green EPC Co.,Ltd.  
**PERIOD :** 15 September 2020



<b>Activity</b>	
Wiring the Electrical System for Corridor	
Floor 08	
<b>Date :</b>	15 September 2563

<b>Activity</b>	
Wiring the Electrical System for Corridor	
Floor 08	
<b>Date :</b>	15 September 2563



<b>Activity</b>	
Wiring the Electrical System for Corridor	
Floor 08	
<b>Date :</b>	15 September 2563

<b>Activity</b>	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 13	
<b>Date :</b>	15 September 2563

*Photographic Progress Works*

**PROJECT:** RENOVATION RIVER GARDEN


**CONSULTANT:** Northcroft (Thailand) Ltd.

**LOCATION:** Charoen Krung 42/1, Bangkok

**CONTRACTOR:** Green EPC Co.,Ltd.

**ACTIVITIES ON SITE:** Electrical Work

**PERIOD :** 15 September 2020

			
<b>Activity</b>		<b>Activity</b>	
Installation of Electrical Pipe Above the ceiling for the Room.			
Floor 13			
<b>Date :</b>	15 September 2563	<b>Date :</b>	

<b>Activity</b>		<b>Activity</b>	
<b>Date :</b>		<b>Date :</b>	

*Photographic Progress Works*


**PROJECT:** RENOVATION RIVER GARDEN  
**LOCATION:** Charoen Krung 42/1, Bangkok  
**ACTIVITIES ON SITE:** Air Conditioning Work

**CONSULTANT:** Northcroft (Thailand) Ltd.  
**CONTRACTOR:** Green EPC Co.,Ltd.  
**PERIOD :** 15 September 2020



<b>Activity</b>	
Nitrogen Test 600 PSI Arae Corridor	
Floor 16	
<b>Date :</b>	15 September 2563

<b>Activity</b>	
Nitrogen Test 600 PSI Arae Corridor	
Floor 16	
<b>Date :</b>	15 September 2563



<b>Activity</b>	
Nitrogen Test 600 PSI Arae Corridor	
Floor 16	
<b>Date :</b>	15 September 2563



<b>Activity</b>	
Fix the Installation Ductwork.	
Floor 11	
<b>Date :</b>	15 September 2563



*Photographic Progress Works*



**PROJECT:** RENOVATION RIVER GARDEN  
**LOCATION:** Charoen Krung 42/1, Bangkok  
**ACTIVITIES ON SITE:** Sanitary and Fire Protection Work

**CONSULTANT:** Northcroft (Thailand) Ltd.  
**CONTRACTOR:** Green EPC Co.,Ltd.  
**PERIOD :** 15 September 2020



<b>Activity</b>	
Installation CW,HW Pipe Area Corridor.	
Floor 16	
<b>Date :</b>	15 September 2563

<b>Activity</b>	
Installation CW,HW Pipe Area Corridor.	
Floor 12	
<b>Date :</b>	15 September 2563



<b>Activity</b>	
Installation CW,HW Pipe Area Corridor.	
Floor 16	
<b>Date :</b>	15 September 2563

<b>Activity</b>	
Installation CW,HW Pipe Area Corridor.	
Floor 12	
<b>Date :</b>	15 September 2563

*Photographic Progress Works*

**PROJECT:** RENOVATION RIVER GARDEN

**CONSULTANT:** Northcroft (Thailand) Ltd.

**LOCATION:** Charoen Krung 42/1, Bangkok

**CONTRACTOR:** Green EPC Co.,Ltd.

**ACTIVITIES ON SITE:** Air Conditioning Work

**PERIOD :** 15 September 2020



**Activity**

**Activity**

Fix the Installation Ductwork.


Fix the Installation Ductwork.

Floor 11

Floor 11

**Date :** 15 September 2563

**Date :** 15 September 2563



**Activity**

**Activity**

Fix the Installation Ductwork.

Floor 11


**Date :** 15 September 2563

**Date :**

*Photographic Progress Works*

**PROJECT:** RENOVATION RIVER GARDEN  
**LOCATION:** Charoen Krung 42/1, Bangkok  
**ACTIVITIES ON SITE:** Sanitary and Fire Protection Work

**CONSULTANT:** Northcroft (Thailand) Ltd.  
**CONTRACTOR:** Green EPC Co.,Ltd.  
**PERIOD :** 15 September 2020



<b>Activity</b>		<b>Activity</b>	
Installation CW,HW Pipe Area Corridor.			
Floor 12			
<b>Date :</b>	15 September 2563	<b>Date :</b>	

<b>Activity</b>		<b>Activity</b>	
<b>Date :</b>		<b>Date :</b>	