


Photographic Progress Works



PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Electrical Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 19 September 2020



Activity	
Electrical Wiring Work For The Room.	
Floor 08	
Date :	19 September 2563

Activity	
Electrical Wiring Work For The Room.	
Floor 08	
Date :	19 September 2563



Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 13	
Date :	19 September 2563

Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 13	
Date :	19 September 2563

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN


CONSULTANT: Northcroft (Thailand) Ltd.

LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Air Conditioning Work

PERIOD : 19 September 2020



Activity

Installation of Duct In The Room

Floor 12


Date : 19 September 2563

Activity

Installation of Duct In The Room

Floor 12

Date : 19 September 2563



Activity

Installation of Duct In The Room

Floor 12

Date : 19 September 2563

Activity

Installation of Duct In The Room



Floor 12

Date : 19 September 2563

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Sanitary and Fire Protection Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 19 September 2020





Activity
 Installation CW,HW Pipe For The Main Shaft.
 Floor 16

Date : 19 September 2563

Activity
 Installation CW,HW Pipe For The Main Shaft.
 Floor 16

Date : 19 September 2563



Activity
 Installation CW,HW Pipe For The Main Shaft.
 Floor 16

Date : 19 September 2563

Activity
 Installation CW,HW Pipe For The Main Shaft.
 Floor 16

Date : 19 September 2563