



Photographic Progress Works



PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Electrical Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 26 September 2020



Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 12	
Date :	26 September 2563

Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 12	
Date :	26 September 2563



Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 12	
Date :	26 September 2563

Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 12	
Date :	26 September 2563

Photographic Progress Works



PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Sanitary and Fire Protection Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 26 September 2020



Activity	
Installation CW,HW Pipe For Shaft	
Floor 05	
Date :	26 September 2563

Activity	
Installation CW,HW Pipe For Shaft	
Floor 05	
Date :	26 September 2563



Activity	
Installation CW,HW Pipe For Corridor	
Floor 12	
Date :	26 September 2563

Activity	
Installation CW,HW Pipe For Corridor	
Floor 12	
Date :	26 September 2563

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN


CONSULTANT: Northcroft (Thailand) Ltd.

LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.


ACTIVITIES ON SITE: Air Conditioning Work

PERIOD : 26 September 2020



Activity
Installation of the Exhaust Fan Duct
Floor 08
Date : 26 September 2563

Activity
Inspect The Distance Of The Air Conditioner
Floor 09
Date : 26 September 2563



Activity
Inspect The Distance Of The Air Conditioner
Floor 09
Date : 26 September 2563

Activity
Installation of Air Conditioner
Floor 10
Date : 26 September 2563

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN



CONSULTANT: Northcroft (Thailand) Ltd.

LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Air Conditioning Work

PERIOD : 26 September 2020



Activity	
Installation of Air Conditioner	
Floor 10	
Date :	26 September 2563

Activity	
Installation of Air Conditioner	
Floor 10	
Date :	26 September 2563



Activity	
Installation of Air Conditioner	
Floor 10	
Date :	26 September 2563

Activity	
Date :	