


Photographic Progress Works



PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Electrical Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 29 September 2020



Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 10	
Date :	29 September 2563

Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 11	
Date :	29 September 2563




Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 10	
Date :	29 September 2563

Activity	
Installation of Electrical Pipe Above the ceiling for the Room.	
Floor 12	
Date :	29 September 2563

Photographic Progress Works



PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Sanitary and Fire Protection Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 29 September 2020



Activity	
Insulated Cold And Hot Water Pipes At the Corridor	
Floor 16	
Date :	29 September 2563

Activity	
Insulated Cold And Hot Water Pipes At the Corridor	
Floor 16	
Date :	29 September 2563



Activity	
Installation CW,HW Pipe For Shaft	
Floor 12	
Date :	29 September 2563

Activity	
Installation CW,HW Pipe For Corridor	
Floor 12	
Date :	29 September 2563

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN


CONSULTANT: Northcroft (Thailand) Ltd.

LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.


ACTIVITIES ON SITE: Air Conditioning Work

PERIOD : 29 September 2020



Activity	
Installation Support For Air Conditioner Pipe	
Floor 15	
Date :	29 September 2563

Activity	
Installation Support For Air Conditioner Pipe	
Floor 15	
Date :	29 September 2563



Activity	
Installation of Air Conditioner	
Floor 10	
Date :	29 September 2563

Activity	
Installation of Air Conditioner	
Floor 10	
Date :	29 September 2563

Photographic Progress Works

PROJECT: RENOVATION RIVER GARDEN


CONSULTANT: Northcroft (Thailand) Ltd.

LOCATION: Charoen Krung 42/1, Bangkok

CONTRACTOR: Green EPC Co.,Ltd.

ACTIVITIES ON SITE: Electrical Work

PERIOD : 29 September 2020



Activity

Activity

Installation of Electrical Pipe Above the ceiling for the Room.
Floor 12

Installation of Electrical Pipe Above the ceiling for the Room.
Floor 12

Date : 29 September 2563

Date : 29 September 2563



Activity

Activity

Inspect The Installtion Of The Main Electricity Paid Into The Room
Floor 08

Inspect The Installtion Of The Main Electricity Paid Into The Room
Floor 08

Date : 29 September 2563

Date : 29 September 2563

Photographic Progress Works


PROJECT: RENOVIATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Sanitary and Fire Protection Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 29 September 2020



Activity	
Inspect The Installation Of Hot Water, Cold Water Pipes Floor 16	
Date :	29 September 2563

Activity	
Inspect The Installation Of Hot Water, Cold Water Pipes Floor 16	
Date :	29 September 2563



Activity	
Inspect The Installation Of Hot Water, Cold Water Pipes Floor 16	
Date :	29 September 2563

Activity	
Inspect The Installation Of Hot Water, Cold Water Pipes Floor 16	
Date :	29 September 2563

Photographic Progress Works


PROJECT: RENOVATION RIVER GARDEN
LOCATION: Charoen Krung 42/1, Bangkok
ACTIVITIES ON SITE: Air Conditioning Work

CONSULTANT: Northcroft (Thailand) Ltd.
CONTRACTOR: Green EPC Co.,Ltd.
PERIOD : 29 September 2020



Activity	
Inspect The Distance Of The Air Conditioner	
Floor 11	
Date :	29 September 2563

Activity	
Inspect The Distance Of The Air Conditioner	
Floor 11	
Date :	29 September 2563



Activity	
Inspect The Distance Of The Air Conditioner	
Floor 10	
Date :	29 September 2563

Activity	
Inspect The Distance Of The Air Conditioner	
Floor 10	
Date :	29 September 2563